Inspector: Katie Helton

Investigation Date/Time: 12/5/2017 9:30 AM

Facility: SolowPower Permit# 433.051

PHOTOS

CAPTIONS/PHOTO LOCATION SCREEN CAPTURES



Remaining wastewater in storage tanks prior to to being treated. According to of SoloPower, tank on left and right are closer to a base with metals.



Remaining acidic metals wastewater prior to being treated.

Inspector: Katie Helton Investigation Date/Time: 12/5/2017 9:30 AM Facility: SolowPower Permit# 433.051

PHOTOS

CAPTIONS/PHOTO LOCATION SCREEN CAPTURES



Wastewater still in the pH adjustment tank.

Inspector: Katie Helton	Investigation Date/Time: 12/5/2017 9:30 AM
Facility: SolowPower Permit# 433.051	

PHOTOS	CAPTIONS/PHOTO LOCATION SCREEN CAPTURES

Inspector: Katie Helton	Investigation Date/Time: 12/5/2017 9:30 AM
Facility: SolowPower Permit# 433.051	

PHOTOS	CAPTIONS/PHOTO LOCATION SCREEN CAPTURES

Inspector: Katie Helton	Investigation Date/Time: 12/5/2017 9:30 AM
Facility: SolowPower Permit# 433.051	

PHOTOS	CAPTIONS/PHOTO LOCATION SCREEN CAPTURES

Inspector: Katie Helton	Investigation Date/Time: 12/5/2017 9:30 AM
Facility: SolowPower Permit# 433.051	

PHOTOS	CAPTIONS/PHOTO LOCATION SCREEN CAPTURES

Inspector: Katie Helton	Investigation Date/Time: 12/5/2017 9:30 AM
Facility: SolowPower Permit# 433.051	

PHOTOS	CAPTIONS/PHOTO LOCATION SCREEN CAPTURES

Inspector: Katie Helton	Investigation Date/Time: 12/5/2017 9:30 AM
Facility: SolowPower Permit# 433.051	

PHOTOS	CAPTIONS/PHOTO LOCATION SCREEN CAPTURES